
CAMBRIDGE CHAPIN FIELD AIRPORT

WASHINGTON CO.



Runways	Coordinates
---------	-------------

07/25: 2100 x 71 (TURF-F) Latitude 43-03-00.277N 05/23: 2200 x 80 (TURF-F) Longitude 073-21-58.401W

Navigation

Services

Communications

CTAF/U 122.9 Elevation 508 02 N NM from City

Instr Approach NONE

Owner/Manager

MR DEAN CHAPIN Fuel Owner Manager MR DICK RECORD Airframe Repairs NONE NONE

4 SOUTH UNION Engine

CAMBRIDGE NY 12816 Attended **UNATNDD**

Phone (518) 677-3866 Airline Airport NO Fax Transportation

E-mail Food Web site Lodging

FBO (Location)

CHAPIN FIELD FBO RWY 5/23 & RW 7/25 SOFT AND WET MARCH -(518) 686-5744 JUNE. RW 7/25 DISPLACED THRESHOLD MARKED WITH STRIPED CYLINDERS. LIGHTED 5' FENCE AT RWY 25 END.

18

Remarks